OUT61153

21

10 Z

P 082050Z FEB 67

FM NPIC WASHDC

TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEPJS/DIA WASHDC
RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHBC
RUWBKNA/15TH AF MARCH AFB RIVERSIBE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 9817.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)

2D AF (FOR DI).

- 1. CAMERA B-15 WAS USED ON MISSION G-946 FLOWN ON 6 FEBRUARY 1967. PROCESSING WAS ACCOMPLISHED BY NAV RECONTECH SUPPCEN.
 - 2. ORIGINAL NEGATIVE:
 - A. DENSITY AND RESOLUTION ARE GOOD.

B. 9R SIDE: ROLLER CHATTER IS PRESENT ON BOTH EDGES OF Sanitized THE FILM THROUGHOUT THE MISSION. PLUS DENSITY OVALS OCCUR INTERMITTENTLY THROUGHOUT THE MISSION. BEGINNING WITH FRAME 1501 THERE ARE TWO ROWS OF PLUS DENSITY STREAKS 2.5 AND 5.2 INCHES FROM THE INBOARD EDGE WHICH CONTINUE TO THE END OF THE MISSION. FOGGED AREAS RANGING FROM 0.25 TO 0.75 INCHES WIDE AND FROM 1.5 TO 2 INCHES LONG OCCUR IN FRAMES 132, 143, 445, 451, 489, 719, 1284, AND 1590. THESE AREAS ARE PRESENT IN THE FORMAT ALONG THE OUTBOARD EDGE AND EXTEND DIAGONALLY TOWARDS THE CENTER OF THE FRAME. A HEAT SPLICE IS PRESENT IN FRAME 1086.



| | | 9 FEB 19 | 67_ | : |
|---|--------------|---|--------|---|
| | DISTRIBUTION | | | |
| | Cy Ng. | Office | Action | |
| | | File | | |
| | 7 | os | | |
| | | | | |
| | | SEC BR | | |
| | | TDS | | |
| | | CSD | | |
| | | IPD | | |
| | | PD | | |
| | | PSD | | _ |
| | | PSD-ICB | | |
| 1 | 345 | | | - |
| | 1/10 | IAD | | |
| ı | | · — · · · · · · · · · · · · · · · · · · | | |
| | | PAG | | |
| ŀ | | DIAXX-4 | | |
| | | SPAD | | |
| | | NOA-LO | | |
| | | DIA-/.P | | |
| | | | | |
| | | | 1 | l |

CROUP 1
Excluded from automatic downgrading and description

- C. 9L SIDE: EDGE STATIC ON THE IMPOARD EDGE AND PLUS
 DENSITY OVALS 1.25 INCHES FROM THE INBOARD EDGE ARE PRESENT
 INTERMITTENTLY THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE
 IS PRESENT IN FRAME 873 AND A HEAT SPLICE IS PRESENT IN FRAME
 1089. THIS FRAME ALSO HAS PROCESSING STREAKS AND HANDLING
 MARKS ASSOCIATED WITH THE HEAT SPLICE.
- D. BOTH SIDES: THE LAST TITLED FRAME IS 2173. THE DATA BLOCK FRAME COUNTER SKIPPED A NUMBER BETWEEN TITLED FRAME 2169 AND TITLED FRAME 2170. SMEAR CAUSED BY VEHICLE MANEUVERING WAS RECORDED ON 14 FRAMES. FRAMES 2 AND 3 APPEAR UNDEREXPOSED. A MINUS DENSITY AREA 0.25 INCHES SQUARE EXTENDS FROM THE DATA BLOCK INTO THE FORMAT.
 - 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURRED APPROXIMATELY 10 PERCENT OF THE MISSION.

GP-1

SECRET

-END OF MESSAGE-